

02975.000160

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

|                                   |   |                        |
|-----------------------------------|---|------------------------|
| In re Patent of:                  | ) |                        |
|                                   | : | Examiner: Mark O. Budd |
| KOSUKE FUJIMOTO                   | ) |                        |
|                                   | : | Group Art Unit: 2834   |
| Appl. No.: 10/809,540             | ) |                        |
|                                   | : | Confirmation No.: 6127 |
| Filed: March 26, 2004             | ) |                        |
|                                   | : |                        |
| For: CONTROL APPARATUS CAPABLE OF | ) |                        |
| LOW-SPEED DRIVING OF VIBRATION    | : |                        |
| TYPE DRIVING APPARATUS, ACTUATING | ) |                        |
| APPARATUS USING THE CONTROL       | : |                        |
| APPARATUS, CONTROL METHOD         | ) |                        |
| CAPABLE OF LOW-SPEED DRIVING OF   | : |                        |
| VIBRATION TYPE DRIVING APPARATUS, | ) |                        |
| AND STORAGE MEDIUM STORING        | : |                        |
| PROGRAM INCLUDING PROGRAM CODES   | ) |                        |
| CAPABLE OF REALIZING THE CONTROL  | : |                        |
| METHOD                            | ) |                        |
|                                   | : |                        |
| Patent No.: US 7,129,618 B2       | ) |                        |
|                                   | : |                        |
| Issued: October 31, 2006          | ) | May 7, 2008            |

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. However, the Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Mark A. Williamson/

---

Mark A. Williamson  
Attorney for Patentees  
Registration No. 33,628

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200

MAW:eyw

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 7,129,618 B2

DATED : October 31, 2006

INVENTOR(S) : FUJIMOTO

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE, AT ITEM (57), Abstract:

Line 11, "controls" should read --control--.

IN THE DRAWINGS:

Sheet No. 34 of 41, Figure 38, "PERIDO" (all occurrences) should read --PERIOD--.

COLUMN 3:

Line 5, "means," should read --means--.

COLUMN 4:

Line 50, "signal" should read --signals--.

Line 54, "vibration" should read --vibrations--.

COLUMN 5:

Line 20, "yet" should read --yet another--.

Line 44, "signal" should read --signals--.

COLUMN 10:

Line 57, "contact" should read --contact with--.

COLUMN 14:

Line 67, "difference" should read --different--.

COLUMN 15:

Line 5, "ad" should read --and--.

Line 48, "circuits" should read --circuit--.

**MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

**PATENT NO.** US 7,129,618 B2

No. of add'l. copies  
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 7,129,618 B2

DATED : October 31, 2006

INVENTOR(S) : FUJIMOTO

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16:

Line 63, "ends" should read --end--, and "sides of" should read --side of each of--.

Line 65, "other ends" should read --the other end--.

Line 66, "sides of" should read --side of each of--.

COLUMN 17:

Line 4, "ends" should read --end--, and "sides of" should read --side of each of--.

Line 8, "ends" should read --end--, and "sides of" should read --side of each of--.

Line 11, "diving" should read --driving--.

COLUMN 19:

Line 23, "difference" should read --different--.

COLUMN 28:

Line 67, "signal" should read --signals--.

COLUMN 29:

Line 6, "vibration" should read --vibrations--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 7,129,618 B2

No. of add'l. copies  
@ 30¢ per page

Staple  
Here  
Only!

PRINTERS TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 7,129,618 B2

DATED : October 31, 2006

INVENTOR(S) : FUJIMOTO

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 30:

Line 46, "vibration" should read --vibrations--.

Line 54, "wherein," should be deleted.

**MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

**PATENT NO. US 7,129,618 B2**

No. of add'l. copies  
@ 30¢ per page

